



Decorative & Architectural

Technical Data Sheet

D315-STD (Rev 1/2021)

PRODUCT NAME: PENETRATING LIQUID

Generic Type: Long Oil Alkyd.

General Description:

A thin low viscosity resin solution having a very good penetrating ability to bind powdery residues to provide a satisfactory base to accept further coats of paint.

Recommended Uses:

As a pre-treatment on exterior or interior surfaces where powdery residues remain after scraping and wire-brushing of old friable lime-wash, oil-bound distemper or emulsion paint.

Features/Benefits:

- Excellent binder for "powdery" walls
- Extends the life for topcoats

Limitations of Use:

May cause discoloration of some types of wood. Should not be used directly on new or unpainted cement based.

Suggested Primer:
Not Required

Product Data:

Spreading Rate:
9 - 11 m² per 0.95 litre container depending on the porosity and texture of the surface.

Drying Time:
Touch Dry: 3 – 4 hrs.
Over Coat: 16 hrs.

Application:
Brush or roller

Gloss: Glossy
Colour: Clear

Thinner/Cleaner:
Kaleidoscope Thinner 2000

Flash Point:
39°C (102°F)



A Member of: kplgroup

Head Office (868) 638-2213/6
Chanka Trace, El Socorro Ext. Rd
San Juan, Trinidad, W.I.

South Branch (868) 658-1818
#99 Market Street, Marabella,
Trinidad, W.I.

©2021 Kaleidoscope Paints Ltd • info@kplgroup.com • www.kscopaints.com

ISO 9001 DOC Control #KPL-QD-19/REV 01-1 TDS Revision #1/2021



Decorative & Architectural

Technical Data Sheet

D315-STD (Rev 1/2021)

PRODUCT NAME: PENETRATING LIQUID

General Surface Preparation & Directions for Use

Remove all loose and peeling paint with scrapers or high pressure rinse. Surface must be dry before application of this product.

Use plastic or rubber gloves and goggles to protect the hands and eyes. Restrict application to an area not more than 2000 cm2. (approx. 2 ft2) at a time. Flow on a heavy coat, using a soft brush and stroking in one direction only. Allow Paint Remover to remain on surface, for 5 - 15 mins, until the coating is completely blistered before attempting to remove. Further applications may be necessary with some tough coatings. Use paint scraper/wire wool to remove the loosened coating while flushing with water. Finally abrade the surface free of all residues and allow drying.

CAUTION: Do not shake can. Avoid contact with skin or eyes which may be irritated. Avoid prolonged or repeated breathing of vapor or contact with skin. Contact with flame or hot surface may produce toxic gases. Use with adequate ventilation. Wash thoroughly after using. If contact results in stinging or smarting, flush skin or eyes with plenty of water. Get medical attention urgently, if eyes have been in contact.